

**MRI4**


Software-Version: 3.4

DOK-WD-MRI4-2E

Revision: C

This document does not replace the Technical Manual.

# MRI4-2A0AAA




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

# MRI4-2A0AAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

# MRI4-2A0ABA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0ABB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X


**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0ACA




- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A0ACB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A0ADA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A0ADB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A0AEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0AEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0AFA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0AFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0AGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0AGB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0AHA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X



# MRI4-2A0AHB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

# MRI4-2A0AIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0AIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0AKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0AKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X


**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0ALA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X101** – IRIG-B00X
- X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0ALB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0ATA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card


**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals



# MRI4-2A0ATB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0BAA




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

# MRI4-2A0BAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

# MRI4-2A0BBA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0BBB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0BCA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)


**X101** – IRIG-B00X

# MRI4-2A0BCB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A0BDA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A0BDB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A0BEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0BEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0BFA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0BFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0BGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0BGB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0BHA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X



# MRI4-2A0BHB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

# MRI4-2A0BIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0BIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0BKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0BKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0BLA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0BLB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector


# MRI4-2A0BTA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals



# MRI4-2A0BTB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0HAA




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

# MRI4-2A0HAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card


**X101** – IRIG-B00X

# MRI4-2A0HBA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X101** – IRIG-B00X
- X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0HBB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0HCA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)


**X101** – IRIG-B00X

# MRI4-2A0HCB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A0HDA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A0HDB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A0HEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0HEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X


**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A0HFA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X101** – IRIG-B00X
- X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0HFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A0HGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0HGB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A0HHA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X



# MRI4-2A0HHB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

# MRI4-2A0HIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0HIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TI-4: Standard current measuring card

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A0HKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0HKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0HLA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A0HLB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TI-4: Standard current measuring card

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector


# MRI4-2A0HTA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals




# MRI4-2A0HTB




- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TI-4: Standard current measuring card
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1AAA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X101** – IRIG-B00X

# MRI4-2A1AAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

# MRI4-2A1ABA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1ABB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1ACA




- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1ACB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1ADA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A1ADB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A1AEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1AEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1AFA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1AFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1AGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A1AGB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X101** – IRIG-B00X
- X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB


# MRI4-2A1AHA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X




# MRI4-2A1AHB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1AIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1AIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1AKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1AKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1ALA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X101** – IRIG-B00X
- X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1ALB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector


# MRI4-2A1ATA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals




# MRI4-2A1ATB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1BAA




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

# MRI4-2A1BAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

# MRI4-2A1BBA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1BBB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1BCA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1BCB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

# MRI4-2A1BDA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A1BDB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A1BEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1BEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1BFA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1BFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1BGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A1BGB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB


# MRI4-2A1BHA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X




# MRI4-2A1BHB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1BIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1BIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1BKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1BKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1BLA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1BLB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X101** – IRIG-B00X
- X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector


# MRI4-2A1BTA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals




# MRI4-2A1BTB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1HAA




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

# MRI4-2A1HAB




**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

# MRI4-2A1HBA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1HBB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1HCA




- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1HCB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1HDA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector



# MRI4-2A1HDB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, Fiber optics interface, ST Connector

# MRI4-2A1HEA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1HEB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X


**X103** – Profibus-DP, RS485, D-SUB

# MRI4-2A1HFA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X101** – IRIG-B00X
- X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1HFB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, Fiber optics interface, ST Connector

# MRI4-2A1HGA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB

# MRI4-2A1HGB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus RTU / IEC 60870-5-103 / DNP3.0 RTU, RS485, D-SUB


# MRI4-2A1HHA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X




# MRI4-2A1HHB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X

# MRI4-2A1HIA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1HIB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs

**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact


**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X100** – Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)

**X101** – IRIG-B00X

**X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals

# MRI4-2A1HKA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1HKB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1HLA



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector

# MRI4-2A1HLB



**X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs


**X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact

**X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring

**X101** – IRIG-B00X

**X103** – Modbus TCP / DNP3.0 TCP/UDP, Fiber optics interface, LC Connector


# MRI4-2A1HTA



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals



# MRI4-2A1HTB



- X1** – DI8-X1: Wide-range power supply unit, incl. 2 non-grouped digital inputs and 6 grouped digital inputs
- X2** – OR-5: Assembly Group with 5 Relay Outputs + 1 Supervision Contact
- X3** – TIs-4: Standard phase current measuring card and sensitive ground current measuring
- X100** – IEC 61850 / Modbus TCP / DNP3.0 TCP/UDP, Ethernet interface, 100 Mbit/s, RJ45 (BASE100-FX)
- X101** – IRIG-B00X
- X103** – IEC 60870-5-103 / Modbus RTU / DNP3.0 RTU, RS485, Terminals